



! When the arm with rubber bedding is replaced by the improved version, replace both left and right arm !



	Sidem Nr.	Reference nr.
Track Control arm	21972 R	31 12 6 758 513 S1
BMW (E36)	21973 R	31 12 6 758 514 S1

Problem:

- Early wear of rubber bedding Ball Joint.
- Play on ball joint.
- Early wear silent block

Cause:

- Weak connection by rubber between inner and outer bushing.
- When replacing a ball joint, special equipment is needed to press it in the arm to prevent damage.
- Damaged dustcover.
- Wrong method of mounting silent block.

Solution:

- A new ball joint is progressed without the rubber core.
- A cover is added to protect the pin and the dustcover during transport and storage.
- A document is added with mounting tips.

