



**Audi
Track control arm**

Sidem Nr.	Reference nr.
37675	4D0 407 151 P

Original:



Problem:

- Play on Ball joint

Cause:

- Water infiltration in the ball joint gives early wear.
- Bad closure of the dustcover.
- Unprotected surface of the cone is causing early forming of rust.

Solution

- Design of a new dustcover according the latest OE model.
- Adjusting the pin to ensure a better fit of the dustcover.

Improved:

