



SIDEM SOLUTIONS



Improved track control arm Audi, Skoda & Volkswagen



	SIDEM	TOEPASSING	N° OE
37675	track control arm	Audi A4/S4	4D0 407 151 P
		Audi A6	
		Audi A8	
		Skoda Superb	
		VW Passat IV/V	

PROBLEM

- Play on ball joint

CAUSE

- Waterinfiltration in the ball joint by not sufficient sealing of the dustcover.



SOLUTION

- A new dustcover is designed with a perfect fit along the rod.
- A new balpin is designed with an improved neck shape to ensure tight closing of the dustcover during movement.

RESULT

- Significant longer lifetime with constant driving comfort.

