



**Mercedes  
Ball Joint**

**Sidem Nr.  
49383**

**Reference nr.  
211 330 03 35**


**Problem:**

- Difficult mounting
- Location of “positioning pin” is not OK.

**Original:**



**Improved:**



**Solution:**

- Use of specific drilling tool to ensure the correct drilling position and angle.
- Test caliber is used to apply 100% control on correct position pin.