



## Mounting advise for ball joints with protection plate

## Problem:


- Infiltration of water or dirt on top of dustcover
- Wear of the top of the dustcover, by turning against a rough surface

## Cause:

• Protection plate for top DC is not fitted

## Solution:

- The protection plate creates a smooth surface for the top of the dustcover, making sure that the top of the dustcover seals perfectly against this plate.
- Always install the protection plate when there's an original one from the constructor. The protection plate protects the top of the dustcover for wear.
- If there's a clip on it be sure to fit it always in the notch in the steering knuckle, so the protection plate stays in place.



Protection plates occur on cars with ball joints with cylindrical pins mainly on Renault applications.

