



Old design

Undercut where the top of the Dust Boot can slide in.



6534

6535

Renault-Opel-Vauxhall-Nissan Tie Rod End **OE Number** 48520 00QAK 48520 00QAL

Problem:

 Possibility of shooting the top of the DC in the neck while installing the Tie Rod End

Cause:

• Neck on ballpin without mechanical seat

Solution:

 The neck on the ballpin is removed on The ballpin, so no possibility anymore for the DC to shoot in the neck



